


Scie Circulaire N5900B



2003/04
N5900B

Scie Circulaire N5900B



Item	Parts_No.	Parts_Description	Qty	Unit
1	251644-1	HEX. FLANGE HEAD BOLT M8X20	1	PC.
2	224301-4	OUTER FLANGE 42	1	PC.
003-1	224302-2	INNER FLANGE 42	1	PC.
4	961202-2	RETAINING RING S-45	1	PC.
005-1	318091-0	SAFETY COVER	1	PC.
6	265031-8	+ COUNTERSUNK HEAD SCREW M6X20	2	PC.
007-1	231846-5	TENSION SPRING 5	1	PC.
008-1	318089-7	BEARING BOX	1	PC.
9	213560-5	O RING 44	1	PC.
10	211228-7	BALL BEARING 6202DDW	1	PC.
11	285809-3	BEARING RETAINER 23-36	1	PC.
12	323955-5	SPINDLE	1	PC.
13	226523-2	HELICAL GEAR 39	1	PC.
14	211088-7	BALL BEARING 6000DDW	1	PC.
15	272230-5	LEVER 54	1	PC.
16	231955-0	RING SPRING 12	1	PC.
17	252134-7	HEX. NUT M8	1	PC.
18	331568-8	PIPE 9	1	PC.
19	941201-0	FLAT WASHER 8	1	PC.
020-1	188420-9	BLADE CASE SET	1	PC.
020-1	263005-3	RUBBER PIN 6	1	PC.
020-1		INC. 21	0	
21	819064-1	MAKITA MARK	1	PC.
22	266237-1	CAP SQUARE NECK BOLT M8X90	1	PC.
23	266026-4	TAPPING SCREW BIND CT 4X12	2	PC.
024-1	345760-0	COVER PLATE	1	PC.
025-1	251350-8	+ COUNTERSUNK HEAD SCREW M6X28	1	PC.
026-1	262564-4	RUBBER SLEEVE 6	1	PC.
27	233264-3	COMPRESSION SPRING 5	1	PC.
28	344844-1	SHAFT LOCK	1	PC.
29	211236-8	BALL BEARING 6002DDW	1	PC.
30	267164-5	FLAT WASHER 15	1	PC.
31	240003-4	FAN 80	1	PC.
32	516818-4	ARMATURE ASS'Y 220V	1	PC.
32		INC. 29-313334	0	
33	681630-2	INSULATION WASHER	1	PC.
34	211066-7	BALL BEARING 6200LLB	1	PC.
35	417114-2	BAFFLE PLATE	1	PC.
36	596208-7	FIELD ASS'Y 220V	1	PC.
36	654020-2	RING TERMINAL	2	PC.
36	654502-4	CONNECTOR P-2	2	PC.
37	266044-2	TAPPING SCREW 5X60	2	PC.
38	152612-6	GRIP 36 COMPLETE	1	PC.
39	850732-7	NAME PLATE N5900B	1	PC.
41	233284-7	COMPRESSION SPRING 5	1	PC.
42	651984-1	SWITCH TG71B-2	1	PC.
43	417115-0	SWITCH LEVER	1	PC.
44	265995-6	TAPPING SCREW 4X18	5	PC.
45	911273-9	PAN HEAD SCREW M5X50	4	PC.
46	181044-0	CARBON BRUSH CB-153	1	SET
47	643650-4	BRUSH HOLDER CAP 6.5-13.5	2	PC.
048-1	151848-4	MOTOR HOUSING COMPLETE	1	PC.
048-1	643653-8	BRUSH HOLDER 6.5-13.5	2	PC.
49	645200-1	NOISE SUPPRESSOR	1	PC.
050-1	682564-2	CORD GUARD	1	PC.
051-1	665865-3	POWER SUPPLY CORD 1.0-2-2.5	1	PC.
52	687052-4	STRAIN RELIEF	1	PC.
53	265995-6	TAPPING SCREW 4X18	2	PC.
54	417118-4	HANDLE COVER	1	PC.

Scie Circulaire N5900B



55	934301-3	WING NUT M6	1	PC.
56	231139-0	COMPRESSION SPRING 9	1	PC.
57	257669-3	SLEEVE 6	1	PC.
58	253047-5	FLAT WASHER 6	1	PC.
59	251919-8	CAP SQUARE NECK BOLT M6X20	1	PC.
60	168389-3	BASE	1	PC.
61	266330-1	FLAT HEAD SQ. NECK BOLT M6X16	1	PC.
62	251221-9	+ PAN HEAD SCREW M6	1	PC.
63	924306-1	WING BOLT M6X10	1	PC.
64	253047-5	FLAT WASHER 6	1	PC.
65	942151-2	SPRING WASHER 6	1	PC.
66	934301-3	WING NUT M6	1	PC.
67	252014-7	HEX. LOCK NUT M6-10	1	PC.
A01	164367-1	GUIDE RULE	1	PC.
A02	782016-4	OFFSET WRENCH 13	1	PC.
A03-1	A-89866	TCT SAW BLADE 235X30X20T	1	PC.
A04	193068-4	JOINT SET	1	SET
E01	417117-6	LOCK-OFF BUTTON	1	PC.
E02	415437-2	ROLLER PIN 6	2	PC.
E03	415438-0	ROLLER 20	2	PC.
E04	345759-5	LEVER 98	1	PC.
E05	231847-3	TENSION SPRING 6	1	PC.
E06	911123-8	PAN HEAD SCREW M4X14	1	PC.
E07	419643-1	SPRING HOLDER	1	PC.
E08	266192-7	TAPPING SCREW 4X14	1	PC.